



Cover



Front Walkway---pavers



Driveway---cracked, recommend repair or replacement



Exterior Outlet---seal around box



Walkway---concrete, cracked and deteriorating also trip hazard



Rear Stairs---supports appear to be in direct contact with soil, also depression in pavers.



Downspouts-----extend away from foundation



Radon System---in basement



Water Meter -----in closet



Basement---wet bar



Basement---office



Electric---Main Panel in basement---200
amps estimate



Basement Stairs---install safety rail



Sun Room---off kitchen



Family Room---Gas fire place, direct vent



Hall Bath---2 floor



Master Bath---2 floor, tub working at time of inspection